


## **Human Factors Issues in** U.S. Army Shadow UAV System Ames Research Cen









Susan R. Dowell **U.S. Army Aeroflightdynamics Directorate Army/NASA Rotorcraft Division** Moffett Field, CA

NASA Human Factors Symposium ♦ October 20, 2004



### **Outline**



- U.S. Army UAV Operators (96U MOS)
  - Demographics
  - Operator Training
- Shadow Tactical UAV
  - Current Interface
  - Identified Human Factors Issues
- HF Research Conducted by HSI group
- Current Research
- Future Goals for UAV operations



## Why UAVs?





### [In response to a recent shotdown incident in Fallujah...]

"A piece of fiberglass and aluminum held up in front of a camera is just not the same as a U.S. soldier or pilot."

Dyke Weatherington UAV Task Planning Force, Pentagon



## **Army UAV Operator: 96U MOS**





- Some have college degrees
- Secret security clearance
- •Attrition = 30%
- Must pass flight physical

- 18 23 years old
- Top 5% ASVAB scores





## **Major Duties of UAV Operator**





## Supervises and Operates UAV

- Mission planning
- Launch and recovery
- Remotely piloting
- Mission sensor/payload operations
- Tactical ID
- Minor air frame repair



# Operator Training: Ft. Huachuca, AZ



### 23 Week Course:

- Private Pilot Ground School
- Flight Line Operations
- Intelligence Common Core (Tactical ID)
- Payload Operator Classroom
- Vehicle Operator Classroom
- Simulator Training
- Preflight/Engine Start Lab
- Flight Training



### **Shadow 200 TUAV**





Intell, search, recon missions

Mission duration 4hrs.

Max. altitude 14,000 ft. MSL

**Endurance speed: 65-85 knts** 

Cost = \$250,000 with payload


\$1M

- ✓ Over 10,000 flight hours in Operation Iraqi Freedom
- ✓ Approaching 2500 flight hours/mo. in the theater
- ✓ DoD will spend \$2.2B on UAVs in FY 05



# Mission Planning: Payload Operator Display






- Video feed with selected payload overlays
- Manipulation of payload (GUI/joystick)
- Icons borrowed from digital camera design
- North up map
- Threat/target
   overlays design
   much like
   drawing tools in
   Microsoft
   .



# **AVO Display: AV Control Panel**



- Preset waypoint missions interrupted 90% of the time
- Attitude Indicator pitch/roll, artificial horizon
- Operator can only command heading, roll, speed, altitude (slider bars)

Values will turn orange if lose

comm with AV








## **UAV GCS Interface Challenges**



- Hardware
  - Keyboard feedback
  - Joystick
- Display Menus
  - Architecture (depth)
  - Organization
  - Size- (Fitt's Law)
- Mode Awareness
  - Dynamic Re-tasking
- North up map
- Correlating map to video image
- TALS landing waive off






### **HSI UAV Research**



- Payload symbology assessment
  - Baseline compass rose vs. heading tape





Funded by Army S & T performed in the joint Army/NASA Rotorcraft Division 11



### **HSI UAV Research**



- HMD utilized for sensor control and video display
  - Head-slaved sensor
- 3-D audio vs. stereo vs. mono alerting for ground targets




Funded by Army S & T performed in the joint Army/NASA Rotorcraft Division



### **HSI UAV Research**






T-CAS like display for UAVs operating in unrestricted airspace









#### **Multi-modal Advanced Interfaces**

#### **Levels of Automation**

Supervisory control and re-entering the control loop

### **Man-Unmanned Teaming**

- Controlling UAV from Apache Longbow
- VMS entry in Summer '05

Safely Operating UAVs in the NAS




### **Future Goals**



- Single operator controlling multiple heterogeneous UAVs
- Common operator interface (400 in the field today!!)
- Portable, intuitive interface for dismounted soldiers and small UAVs
- Advanced interface designs for increased SA and reduced workload (imagery analysis)







# **Questions?**









- Baby wipes are used to clean dusty UAV engines in "sandy places"
- Fuel bladders filled to capacity will expand and explode in severe desert heat
- Mis-keying coordinates has caused UAVs to fly to the wrong hemisphere
- GCS touchscreens were eliminated because moths were flying into the display and activating functions
- One shotdown incident was first discovered by the payload operator seeing gas leak across the camera lens